

Monday, November 14, 2016 2:28:45 PM

Page 1

[illegible]

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Work Order ID 153248

Monday, November 14, 2016 2:28:45 PM

153248

Page 2

Item ID: D212-803-215

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 11/15/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

NR1

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	QC4- 100% Inspect kits for completeness	0.00							
120							DAS 28 9-89	NOV 15 2016	
QC	Memo	0.00							
Quality Control									
130	Packaging	0.00							
130							DAS 27 9-89	DAS 28 9-89	NOV 15 2016
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D212-803-215 Location: _____ PPP Rev: _____								
140	QC21- Final Inspection - Work Order Release	0.00							
140							DAS 21 9-89	NOV 15 2016	
QC	Memo	0.00							
Quality Control									
							DAS 21 9-89	NOV 15 2016	

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation		Disposition			
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : ☐			

Picklist Print

Monday, November 14, 2016 2:28:44 PM

Page 1

Work Order ID: 153248

153248

Parent Item: D212-803-215

D212-803-215

Parent Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016

Required Date: 11/15/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP REV:A 15.07.03 NEW ISSUE DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D5155-043 *D5155-043* Co-Pilot Collective Head Assembly (212/412)		Manufactured	No				Each	4.0000	**	1		NOV 15 2016	DAS 6 27 9-89 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				ST373				4					
				146050				4					
D5156-5 *D5156-5* Face Plate		Manufactured	No				Each	7.0000	**	1		NOV 15 2016	DAS 6 27 9-89 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				ST155				7					
				142334				1					
				145840				6					
D5156-7 *D5156-7* Face Plate		Manufactured	No				Each	7.0000	**	1		NOV 15 2016	DAS 6 27 9-89 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				ST155				7					
				134708				1					
				150383				6					
MS171599 *MS171599* Pin		Purchased	No				Each	16.0000	**	1		NOV 15 2016	DAS 6 27 9-89 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				Return2015				1					
				m123183				1					
				ST315				15					
				m134573				15					

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval 	
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY			
Environment ☐	☐ No Re-verification	Pressure/Forced ☐	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong		
Design ☐	☐ Operator	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐		
Doc/Data ☐	☐ Offset/Setup	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐		
Equip/Tooling ☐	☐ Supplier	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐		
Handling/Pre ☐	☐ Training	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐		
Material ☐	☐ Use for Testing	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐		
Internal Transport ☐	☐ Poor Information	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐		
Tribal Knowledge ☐	☐ Rushing	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐		
LOA ☐	☐ Product Improvement	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐		
Substation ☐	☐ Process Improvement	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐		
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : ☐					
Misidentified ☐	☐ Past Due						

Picklist Print

Monday, November 14, 2016 2:28:44 PM

Page 2

Work Order ID: 153248

153248

Parent Item: D212-803-215

D212-803-215

Parent Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016

Required Date: 11/15/2016

Start Qty: 1.00

Required Qty: 1.00

D5055-3

Manufactured No

Each

3.0000

D5055-3

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST146

3

5/17/2017

145260

3

5.0000

D5055-5

Manufactured No

Each

D5055-5

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST146

5

7/4/2017

148153

5

5.0000

D5055-7

Manufactured No

Each

D5055-7

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST146

5

7/4/2017

148206

5

5.0000

D5055-9

Manufactured No

Each

D5055-9

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST146

5

7/4/2017

148157

5

NOV 15 2016
DAS 6 27
9-89 9-89

NOV 15 2016
DAS 6 27
9-89 9-89

NOV 15 2016
DAS 6 27
9-89 9-89

NOV 15 2016
DAS 6 27
9-89 9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval 	
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY			
Environment ☐	☐ No Re-verification	Pressure/Forced ☐	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong		
Design ☐	☐ Operator	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐		
Doc/Data ☐	☐ Offset/Setup	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐		
Equip/Tooling ☐	☐ Supplier	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐		
Handling/Pre ☐	☐ Training	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐		
Material ☐	☐ Use for Testing	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐		
Internal Transport ☐	☐ Poor Information	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐		
Tribal Knowledge ☐	☐ Rushing	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐		
LOA ☐	☐ Product Improvement	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐		
Substation ☐	☐ Process Improvement	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐		
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____					
Misidentified ☐	☐ Past Due						

Picklist Print

Monday, November 14, 2016 2:28:44 PM

Page 3

Work Order ID: 153248

153248

Parent Item: D212-803-215

D212-803-215

Parent Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016

Required Date: 11/15/2016

Start Qty: 1.00

Required Qty: 1.00

D4411-7

Manufactured No

Each

3.0000

D4411-7

Placard

**

1

DAS 6 27
9-89 9-89
NOV 15 2016

Location

Loc Qty

Loc Code

Return2016

1

132770

1

ST096

2

144495

2

27ET51-T

Purchased

No

Each

2.0000

27ET51-T

Switch

**

1

NOV 15 2016

DAS 6 27
9-89 9-89

Location

Loc Qty

Loc Code

ST580

2

m134599

2

30-037-26

Purchased

No

Each

9.0000

30-037-26

Diode Assembly

**

3

NOV 15 2016

DAS 6 27
9-89 9-89

Location

Loc Qty

Loc Code

ST580

9

m135096

3

m135132

6

30-037-3

Purchased

No

Each

5.0000

30-037-3

Diode Assembly

**

2

NOV 15 2016

DAS 6 27
9-89 9-89

Location

Loc Qty

Loc Code

ST580

5

m135096

5

Monday, November 14, 2016 2:28:44 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Monday, November 14, 2016 2:28:44 PM

Page 4

Work Order ID: 153248

153248

Parent Item: D212-803-215

D212-803-215

Parent Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016

Required Date: 11/15/2016

Start Qty: 1.00

Required Qty: 1.00

AN961-6T NAS1149F0463P Purchased No

Each 120.0000

AN961-6T

Washer

DAS
28
9-89

Location

Loc Qty

Loc Code

ST321

120

123314

120

Each

1.0000

**

NOV 15 2016

DAS
27
9-89

51MXV-5-J

Purchased

No

51MXV-5-J

Switch

DAS
28
9-89

Location

Loc Qty

Loc Code

ST583

1

m135096

1

Each

61.0000

**

NOV 15 2016

DAS
27
9-89

M39029/31-240

Purchased

No

M39029/31-240

Pin

DAS
28
9-89

Location

Loc Qty

Loc Code

ST565

61

m134386

61

Each

64.0000

**

NOV 15 2016

DAS
27
9-89

M39029/32-259

Purchased

No

M39029/32-259

Socket

DAS
28
9-89

Location

Loc Qty

Loc Code

ST565

64

m134386

64

Each

14.0000

**

NOV 15 2016

DAS
27
9-89

M39029/31-228

Purchased

No

M39029/31-228

Pin

DAS
28
9-89

Location

Loc Qty

Loc Code

ST565

14

M127949

14

**

NOV 15 2016

DAS
27
9-89

Monday, November 14, 2016 2:28:45 PM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Monday, November 14, 2016 2:28:45 PM

Page 5

Work Order ID: 153248

153248

Parent Item: D212-803-215

D212-803-215

Parent Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016

Required Date: 11/15/2016

Start Qty: 1.00

Required Qty: 1.00

M39029/32-247

Purchased

No

Each

16.0000

2

M39029/32-247

**

NOV 15 2016
DAS 6 27
9-89

Socket

DAS
28
9-89

Location

Loc Qty

Loc Code

ST565

16

M134575

16

MS21042L06

Purchased

No

Each

91.0000

3

MS21042L06

**

NOV 15 2016
DAS 6 27
9-89

Nut

DAS
28
9-89

Location

Loc Qty

Loc Code

ST303

91

m135766

91

MS21042L3

Purchased

No

Each

2,106.000

1

MS21042L3

**

NOV 15 2016
DAS 6 27
9-89

Nut

DAS
28
9-89

Location

Loc Qty

Loc Code

FP001

7

M130922

7

GA

200

m134360

108

m135135

92

OVER007

1200

m135945

600

M136044

600

ST303

699

m135530

99

m135767

600

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QS1042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : ☐			

Picklist Print

Monday, November 14, 2016 2:28:45 PM

Page 6

Work Order ID: 153248

153248

Parent Item: D212-803-215

D212-803-215

Parent Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016

Required Date: 11/15/2016

Start Qty: 1.00

Required Qty: 1.00

MS21044N04

Purchased

No

Each

31.0000

MS21044N04

Nut

DAS
28
9-89

Location

Loc Qty

Loc Code

ST301

25

m135530

25

ST302

6

m132677

6

Each

12.0000

MS21919WDG10

Purchased

No

MS21919WDG10

Clamp

DAS
28
9-89

Location

Loc Qty

Loc Code

ST293

12

m128993

12

Each

10.0000

MS21919WDG19

Purchased

No

MS21919WDG19

Clamp

DAS
28
9-89

Location

Loc Qty

Loc Code

ST292

10

m135133

10

Each

4.0000

MS24523-27

Purchased

No

MS24523-27

Switch

DAS
28
9-89

Location

Loc Qty

Loc Code

ST290

4

m135055

4

**

**

**

**

NOV 15 2016

DAS
6
9-89

DAS
27
9-89

NOV 15 2016

DAS
6
9-89

DAS
27
9-89

NOV 15 2016

DAS
27
6 9-89

NOV 15 2016

DAS
27
6 9-89

Monday, November 14, 2016 2:28:45 PM

Shop Packet Print

Page 6

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QS1042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
				Lead hand / Supervisor Approval Verification					
				QC / QA Coordinator Approval					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Monday, November 14, 2016 2:28:45 PM

Page 8

Work Order ID: 153248

153248

Parent Item: D212-803-215

D212-803-215

Parent Item Name: Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412

Start Date: 11/14/2016

Required Date: 11/15/2016

Start Qty: 1.00

Required Qty: 1.00

MS3126E16-99P

Purchased

No

Each

6.0000

MS3126F16-99P

**

Socket
DAS 28
9-89

Location

Loc Qty

Loc Code

ST272

6

m134630

6

Each

0.0000

MS3120E16-99S

Purchased

No

MS3120F16-99S

**

Socket

MS3373-A1

Purchased

No

Each

3.0000

MS3373-A1

**

Strip

Location

Loc Qty

Loc Code

ST272

3

m135055

3

Each

1,072.000

NAS1149D0363J

Purchased

No

NAS1149D0363.J

**

Washer

Location

Loc Qty

Loc Code

GA

364

m134055

364

ST263

708

m135864

708

DAS 6 27
9-89 9-89
NOV 15 2016

DAS 27
9-89
136134

DAS 6 27
9-89 9-89
NOV 15 2016

DAS 6 27
9-89 9-89
NOV 15 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D212-803 REV. D AND INSTRUCTIONS
FOR CONTINUED AIRWORTHINESS ICA-D212-803 REV. 3 OR LATER APPROVED REVISION
REF. FAA STC: SR02233SE

1.0 PURPOSE

The purpose of the DSI is to amend the installation of the D4410-041/-043/-045 Co-Pilot Collective Head Assembly and the D5046-041/-043/-045 Co-Pilot Collective Head Assembly on the Collective Stick of the Bell 205/212/412 model aircraft for DXXX-803-0XX at CHG 003 and later and the DXXX-803-1XX at CHG 002 and later.

2.0 PROCEDURE

2.1 To install DXXXX-041/-043/-045 Co-Pilot Collective Head Assembly onto Collective Stick Assembly (Bell p/n 205-001-117-1 for 205, Bell p/n 212-001-117-1 for 212/412 and Bell p/n 212-001-171-001 for Eagle Single), position the Head Assembly on the Collective Stick Assembly so that it is angled away from the door and does not contact the pilot's leg. Transfer drill the mounting hole on the Collective Stick Assembly to the desired location on the neck of the DXXXX-041/-043/-045 Collective Head.

2.2 To adjust the position of the DXXXX-041/-043/-045 Collective Head Assembly, it is acceptable to remove 1/2" to 3/4" off of the neck as desired.

2.3 Wet the Collective Head Assembly with Proseal 890 or equivalent and mount using Pin (p/n MS171539 on DXXXX-041 Collective Head or p/n MS171599 on DXXXX-043/-045 Collective Head) per Figure 1. Apply Aircraft Primer to Pin.

3.0 WEIGHT AND BALANCE

Aircraft Weight and Balance are not affected by this change.

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 153248
8m 16/11/14

A	NEW ISSUE	VS	15.06.24
REV.	DESCRIPTION	BY	DATE
DESIGN	VS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	VS		
CHECKED	HS	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9728	SHEET 1 OF 3
APPROVED	HS	TITLE	SCALE
DE APPR.		LH PIC INSTALLATION	NTS
DATE	15.06.24	COPYRIGHT © 2015 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	




FIGURE 1 - Co-Pilot Collective Head Installation
D4410-041 SHOWN D4410-043/-045 AND D5046-041/-043/-045 SIMILAR)

DESIGN	VS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	VS		
CHECKED	HS	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9728	SHEET 2 OF 3
APPROVED	HS	TITLE	SCALE
DE APPR.		LH PIC INSTALLATION	NTS
DATE	15.06.24	COPYRIGHT © 2016 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

4.0 PARTS LISTS

Amend Parts Lists for the following kits per tables below.

4.1 Large Collective Head Kits

Qty -011	Qty -013	Qty -015	Qty -017	Qty -019	Part Number	Description
X					D205-803-011	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
	X				D205-803-013	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
		X			D212-803-015	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
			X		D212-803-017	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
				X	D212-803-019	LEFT HAND PILOT IN COMMAND, EAGLE SINGLE
1	1				MS171539	PIN
		1	1	1	MS171599	PIN

4.2 Small Collective Head Kits

Qty -111	Qty -113	Qty -115	Qty -117	Qty -119	Part Number	Description
X					D205-803-111	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
	X				D205-803-113	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
		X			D212-803-115	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
			X		D212-803-117	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
				X	D212-803-119	LEFT HAND PILOT IN COMMAND, EAGLE SINGLE
1	1				MS171539	PIN
		1	1	1	MS171599	PIN

4.3 Medium Collective Head Kits

Qty -211	Qty -213	Qty -215	Qty -217	Qty -219	Part Number	Description
X					D205-802-211	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
	X				D205-803-213	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
		X			D212-803-215	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
			X		D212-803-217	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
				X	D212-803-219	LEFT HAND PILOT IN COMMAND, EAGLE SINGLE
1	1				MS171539	PIN
		1	1	1	MS171599	PIN

DESIGN	VS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	VS		
CHECKED	HS	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9728	SHEET 3 OF 3
APPROVED	HS	TITLE	SCALE
DE APPR.		LH PIC INSTALLATION	NTS
DATE	15.06.24	COPYRIGHT © 2015 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

Lori Morris

From: Andrew Hill
Sent: Wednesday, November 09, 2016 9:30 AM
To: David Shepherd; Linda Lacelle; Harvey Siemens
Cc: William Monterroza; Chantal Lavoie; Bill Beckett; Patrick Smith; Victoria Seib; Lori Morris
Subject: RE: Newark/element14 Quote # 29736413

Hello All,

See completed table below.

Andrew Hill | Aircraft Certification Manager - Engineering



823 McTavish Rd NE, Calgary, AB T2E 7G9 Canada

Phone: 403.250.7370 ext 409 | Fax: 403.250.7110

Email: ahill@eaglecopters.com | www.eaglecopters.com

This transmission is confidential and intended solely for the person or organization to whom it is addressed. It may contain privileged and confidential information. If you are not the intended recipient, you should not use, copy, distribute or take any action in reliance on it.

If you have received this transmission in error, please notify the sender at the e-mail address above.

From: David Shepherd
Sent: November-08-16 3:22 PM
To: Linda Lacelle <llacelle@dartaero.com>; Harvey Siemens <hsiemens@dartaero.com>
Cc: William Monterroza <wmonterroza@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>; Bill Beckett <bbeckett@dartaero.com>; Andrew Hill <ahill@eaglecopters.com>; Patrick Smith <psmith@dartaero.com>; Victoria Seib <vseib@dartaero.com>; Lori Morris <lmorris@dartaero.com>
Subject: RE: Newark/element14 Quote # 29736413

Andrew,

As discussed earlier today, please verify and complete the following equivalency table:

Part Number Per IIN-D212-803	Acceptable Equivalent Amphenol Part Number
MS3126E16-99P	PT06SE-16-99P
MS3120E16-99S	PT00SE-16-99S
MS3126E14-19P	PT06SE-14-19P
MS3120E14-19S	PT00SE-14-19S

Victoria,

I haven't heard back from Harvey, but let's assume he would assign you to create the DSI against D212-803. As discussed, once Andrew completes the table above, please get this started.

Regards,
David

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

From: Linda Lacelle
Sent: November-08-16 5:52 AM
To: David Shepherd <dshepherd@dartaero.com>; Harvey Siemens <hsiemens@dartaero.com>
Cc: William Monterroza <wmonterroza@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>; Bill Beckett <bbeckett@dartaero.com>; Andrew Hill <ahill@eaglecopters.com>; Patrick Smith <psmith@dartaero.com>
Subject: RE: Newark/element14 Quote # 29736413

Harvey/David,

If we are going to create a DSI, we might as well add the 3 connectors. The stop ship affects the following:

MIL-DTL-22992, MIL-DTL-26482, MIL-DTL-26500, MIL-DTL-27599, MIL-DTL-38999, MIL-STL-55302, MIL-DTL-83513, MIL-DTL-83723

The only ones that we use are:

MS3120E14-19S
MS3120E16-99S
MS3126E25-19P

The M39029's are also included, but I see no Amphenol commercial equivalent

L

From: David Shepherd
Sent: Monday, November 07, 2016 7:19 PM
To: Andrew Hill <ahill@eaglecopters.com>; Linda Lacelle <llacelle@dartaero.com>; Harvey Siemens <hsiemens@dartaero.com>; Patrick Smith <psmith@dartaero.com>
Cc: William Monterroza <wmonterroza@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>; Bill Beckett <bbeckett@dartaero.com>
Subject: RE: Newark/element14 Quote # 29736413

Harvey,

The next step here is to produce a DSI that lists the electrical parts that we are having trouble procuring and the acceptable alternates. Who are you assigning to produce this DSI? Victoria? I can work with whoever you assign to produce the necessary DSI.

Linda,

Are the two parts below the only parts you are having trouble procuring? Or are there other parts we should be listing on the DSI.

Regards,
David

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval 	
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause			FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____						
Misidentified	☐	Past Due	☐							

From: Andrew Hill
Sent: November-07-16 12:54 PM
To: Linda Lacelle <llacelle@dartaero.com>; Harvey Siemens <hsiemens@dartaero.com>; Patrick Smith <psmith@dartaero.com>
Cc: David Shepherd <dshepherd@dartaero.com>; William Monterroza <wmonterroza@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>
Subject: RE: Newark/element14 Quote # 29736413

Linda,

The Amphenol PT00SE-16-99P is an acceptable alternate for the MS3120E16-99P connector.

Andrew Hill | Aircraft Certification Manager - Engineering



823 McTavish Rd NE, Calgary, AB T2E 7G9 Canada

Phone: 403.250.7370 ext 409 | Fax: 403.250.7110

Email: ahill@eaglecopters.com | www.eaglecopters.com

This transmission is confidential and intended solely for the person or organization to whom it is addressed. It may contain privileged and confidential information. If you are not the intended recipient, you should not use, copy, distribute or take any action in reliance on it. If you have received this transmission in error, please notify the sender at the e-mail address above.

From: Linda Lacelle
Sent: November-07-16 9:44 AM
To: Andrew Hill <ahill@eaglecopters.com>; Harvey Siemens <hsiemens@dartaero.com>; Patrick Smith <psmith@dartaero.com>
Cc: David Shepherd <dshepherd@dartaero.com>; William Monterroza <wmonterroza@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>
Subject: RE: Newark/element14 Quote # 29736413
Importance: High

Hello all,

The commercial equivalent PT00SE-16-99S have been released for the LH PIC issue (MS3120E16-99S), are these also acceptable??

Thx <http://www.amphenol-aerospace.com/pdf/12-070.pdf> - see pg 30

Linda

From: Andrew Hill
Sent: Tuesday, April 12, 2016 2:57 PM
To: Harvey Siemens <hsiemens@dartaero.com>; Linda Lacelle <llacelle@dartaero.com>
Cc: David Shepherd <dshepherd@dartaero.com>; William Monterroza <wmonterroza@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>
Subject: RE: Newark/element14 Quote # 29736413

Linda,

The Amphenol PT06SE-16-99P is an acceptable alternate for the MS3126E16-99P connector

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QS1042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Andrew Hill | Aircraft Certification Manager - Engineering



823 McTavish Rd NE, Calgary, AB T2E 7G9 Canada

Phone: 403.250.7370 ext 409 | Fax: 403.250.7110

Email: ahill@eaglecopters.com | www.eaglecopters.com

This transmission is confidential and intended solely for the person or organization to whom it is addressed. It may contain privileged and confidential information. If you are not the intended recipient, you should not use, copy, distribute or take any action in reliance on it. If you have received this transmission in error, please notify the sender at the e-mail address above.

From: Harvey Siemens
Sent: April-12-16 9:25 AM
To: Andrew Hill <ahill@eaglecopters.com>
Subject: FW: Newark/element14 Quote # 29736413
Importance: High

Would these be the right alternate numbers?

HS

From: Linda Lacelle
Sent: April-12-16 8:31 AM
To: Harvey Siemens <hsiemens@dartaero.com>
Cc: David Shepherd <dshepherd@dartaero.com>; William Monterroza <wmonterroza@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>
Subject: FW: Newark/element14 Quote # 29736413
Importance: High

Good Morning,

The MS3126E16-99P's have been put on ship stop (see attached). We use these in 3 of the LH PIC's and have 3 sold for April 26 (2 per kit). They are suggesting the alternate PT06SE-16-99P. we found some, but need an ok from someone in engineering to use these. Can someone please let us know ?

Thx
Linda

From: Chantal Lavoie
Sent: Monday, April 11, 2016 1:29 PM
To: Linda Lacelle <llacelle@dartaero.com>
Subject: FW: Newark/element14 Quote # 29736413

From: Consolo, Lisa [<mailto:LConsolo@Newark.com>]
Sent: Monday, April 11, 2016 1:23 PM
To: Chantal Lavoie <clavoie@dartaero.com>
Subject: Newark/element14 Quote # 29736413

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : ☐			

Newark/element14 Quote # 29736413 Version # 1
(Please reference this number when placing your order)

Quote placed on: 04-07-2016
Prices valid through: 05-07-2016

Bill to: Dart Aerospace Ltd
1270 Aberdeen St

Ship to: Dart Aerospace Ltd
1270 Aberdeen St

Hawkesbury, ON K6A 1K7

Hawkesbury, ON K6A 1K7

Contact Name: Chantal Lavoie
Contact Phone: 6136325200

Line	SKU	Manufacturer's Part	UOM	Qty	Price	Ext Price
------	-----	---------------------	-----	-----	-------	-----------

1.1	34K0169	PT06SE16-99P	EA/1	6	\$124.10	\$744.60
-----	---------	--------------	------	---	----------	----------

Requested Part # PT06SE16-99P

Description: CIRCULAR CONNECTOR PLUG SIZE 16, 23 POSITION, CABLE; Product

Range:PT-SE Series, MIL-DTL-26482 Series I Equivalent; Circular

Connector Shell Style:Straight Plug; No. of Contacts:23; Circular

Contact Type:Crimp Pin; Insert Rotation:N

Manufacturer's Brand: AMPHENOL INDUSTRIAL

Minimum/Multiple Order Quantity: 1/1

On Hand Inventory: 0

Expected Ship Quantity: 6 , Expected Ship Date: 08/29/16 **

Estimated lead time 138 days when no stock.

RoHS compliant?:

****SPECIAL ORDER ITEM -- NON-CANCELABLE AND NON-RETURNABLE****

Sub Total: \$744.60***

* Stock availability subject to change

** All ship dates are estimated

*** Currency: CND

*** Does not include tax or freight charges

Your #1 source for RoHS compliant products & information.

To place this order, get additional quotes or if you have any questions, we are here for you.

Phone: 1-800-463-9275 || Website: <http://canada.newark.com/>

Terms & Conditions:

<http://canada.newark.com/terms-and-conditions>

We look forward to your business.

*****Disclaimer*****

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QS1042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

The preceding e-mail message (including any attachments) contains information that may be confidential, be protected by the attorney-client or other applicable privileges, or constitute non-public information. It is intended to be conveyed only to the designated recipient(s). If you are not an intended recipient of this message, please notify the sender by replying to this message and then delete it from your system. Use, dissemination, distribution, or reproduction of this message by unintended recipients is not authorized and may be unlawful.

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																											
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval																																																							
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																							
Root Cause		FAULT CATEGORY																																																													
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER :	
Misidentified ☐	Past Due ☐																																																														

Work Order ID 153248***153248***

Page 1

Tuesday, November 15, 2016 9:17:05 AM

Item ID: D212-803-215**Accept*****N900040100*****Setup Start *NS1*****Revision ID:****Stop *NS2*****Item Name:** Left Hand Pilot in Command - Medium/Standard Design, Complete 212/412**Start Date:** 11/14/2016 **Start Qty:** 1.00***1*****Cust Item ID:****Required Date:** 11/15/2016 **Req'd Qty:** 1.00***1*****Customer:****Reference:****Approvals:** **Process Plan:** _____ **Date:** _____ **Tooling:** _____ **Date:** _____**Run Start *NR1*****QC:** _____ **Date:** _____ **SPC (Y/N):** _____ **Date:** _____**Stop *NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
DSI9728	A
IIN-D212-803	D

100

Document Control

0.00

100

DOCUMENT CONTROL

DC

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy blue file and type labels per PPP D212-803-215 CHG001

DAS
21
9-59

NOV 15 2016

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

7. PARTS LIST - MEDIUM COLLECTIVE HEAD KITS

Qty -211	Qty -213	Qty -215	Qty -217	Qty -219	Qty -221	Qty -223	Part Number	Description
X							D205-803-211	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
	X						D205-803-213	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
		X					D212-803-215	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
			X				D212-803-217	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
				X			D212-803-219	LEFT HAND PILOT IN COMMAND, EAGLE SINGLE
					X		D205-803-221	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
						X	D205-803-223	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
1	1						D5155-041	CO-PILOT COLLECTIVE HEAD ASSEMBLY (205)
		1	1				D5155-043	CO-PILOT COLLECTIVE HEAD ASSEMBLY (212)
				1			D5155-045	CO-PILOT COLLECTIVE HEAD ASSEMBLY (EAGLE SINGLE)
					1	1	D5155-047	CO-PILOT COLLECTIVE HEAD ASSEMBLY (205 WITH THE 204-001-290-5 STICK AND THROTTLE ASSY INSTALLED)
1	1			1	1	1	D5156-1	FACE PLATE
1	1			1	1	1	D5156-3	FACE PLATE
		1	1				D5156-5	FACE PLATE
		1	1				D5156-7	FACE PLATE
1	1			1	1	1	D4410-9	TRIGGER
1	1			1	1	1	D5055-1	PLACARD
1	1	1	1	1	1	1	D5055-3	PLACARD
		1	1				D5055-5	PLACARD
		1	1				D5055-7	PLACARD
		1	1				D5055-9	PLACARD
1	1	1	1	1			D4411-7	PLACARD
		1					27ET51-T	SWITCH (ALT P/N 212-075-153-3)
1					1		2PB744-T2	SWITCH
		3					30-037-26	DIODE ASSEMBLY
		2					30-037-3	DIODE ASSEMBLY
1	1			1	1	1	AN565F8H9	SETSCREW
		3					AN961-6T	WASHER
		1					51MXY-5-J	SWITCH
1					1		C100E2-39	SWITCH
17		AR (21)			17		M39029/31-240	PIN
17		AR (21)			17		M39029/32-259	SOCKET
		AR (2)					M39029/31-228	PIN
		AR (2)					M39029/32-247	SOCKET
1	1			1	1	1	MS20253-1-065	PIN
		3					MS21042L06	NUT
1	1			1	1	1	MS21042L08	NUT
1	1	1	1	1	1	1	MS21042L3	NUT
		2					MS21044N04	NUT
1	1	1	1	1			MS21919WDG10	CLAMP
		1	1	1			MS21919WDG19	CLAMP
1	1						MS21919WDG20	CLAMP
		1					MS24523-27	SWITCH
		2					MS24693-S7	SCREW
4	4	4	4	4	4	4	MS24693-24B	SCREW
1	1	1	1	1	1	1	MS27039-1-07	SCREW
		1					MS27212-1-3	TERMINAL BOARD
1					1		MS3126E14-19P	PLUG
1					1		MS3120E14-19S	SOCKET
		2					MS3126E16-99P	PLUG
		1					MS3120E16-99S	SOCKET
		3					MS3373-A1	STRIP
2	2	2	2	2			NAS1149D0363J	WASHER
					2	2	MS24665-289	COTTER PIN
1	1	1	1	1	1	1	D212-803	KIT PAPERWORK

REFERENCE ONLY

4.0 PARTS LISTS

Amend Parts Lists for the following kits per tables below.

4.1 Large Collective Head Kits

Qty -011	Qty -013	Qty -015	Qty -017	Qty -019	Part Number	Description
X					D205-803-011	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
	X				D205-803-013	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
		X			D212-803-015	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
			X		D212-803-017	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
				X	D212-803-019	LEFT HAND PILOT IN COMMAND, EAGLE SINGLE
1	1				MS171539	PIN
		1	1	1	MS171599	PIN

4.2 Small Collective Head Kits

Qty -111	Qty -113	Qty -115	Qty -117	Qty -119	Part Number	Description
X					D205-803-111	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
	X				D205-803-113	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
		X			D212-803-115	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
			X		D212-803-117	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
				X	D212-803-119	LEFT HAND PILOT IN COMMAND, EAGLE SINGLE
1	1				MS171539	PIN
		1	1	1	MS171599	PIN

4.3 Medium Collective Head Kits

Qty -211	Qty -213	Qty -215	Qty -217	Qty -219	Part Number	Description
X					D205-802-211	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
	X				D205-803-213	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
		X			D212-803-215	LEFT HAND PILOT IN COMMAND, COMPLETE KIT
			X		D212-803-217	LEFT HAND PILOT IN COMMAND, MECHANICAL ONLY
				X	D212-803-219	LEFT HAND PILOT IN COMMAND, EAGLE SINGLE
1	1				MS171539	PIN
		1	1	1	MS171599	PIN

DESIGN	VS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	VS		
CHECKED	HS	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9728	SHEET 3 OF 3
APPROVED	HS	TITLE	SCALE
DE APPR.		LH PIC INSTALLATION	NTS
DATE	15.06.24	COPYRIGHT © 2015 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	